

CONVERSATION RECORD

TIME
PM

DATE
13 JULY 1988

TYPE

☐ VISIT

☐ CONFERENCE

☒ TELEPHONE

☒ INCOMING

☐ OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

GEORGE LINDENBURG

ORGANIZATION (Office, dept., bureau, etc.)

TELEPHONE NO.

SUBJECT

LAKE ONTARIO ORDNANCE WORKS

ROUTING

NAME/SYMBOL INT

ED-FH

copy to

ED-T

(file)

SUMMARY

GEORGE CALLED IN A BRIEF UPDATE ON LOOW FIELD WORK. GEORGE SAID THERE WAS A problem with one well, C-3-D; the pH would not go down.

(It may be impacted by the grout)

GEORGE ALSO SAID THAT THERE IS A potential problem with well seals, instead of using cement or concrete to ~~construct~~ construct the seals, the driller used grout.

SCA told ACRES that they had clogged ~~the~~ SCA's decon pad sump and asked Acres to clean it out. This sump is 10' x 40' (?) and 6' to 7' deep & it had about 12 inches of muck on bottom - (all of which could not have been due to ACRES) Acres started to clean it out ^(with buckets) & Kevin stopped them until a pump could be found. Evidently a man climbed down into sump.

ACTION REQUIRED

AND AT FIRST DID NOT even wear a air purifying respirator. ACRES H&S person was at the site of the pump when

NAME OF PERSON DOCUMENTING CONVERSATION

this occurred.

SIGNATURE

Kathleen Older

DATE

14 JULY 88

ACTION TAKEN

SIGNATURE

TITLE

DATE